

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 0 H D B S 1 2 0 0 - 0 0 N P F - 0 3 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T
01 REPORT SOURCE L 6 0 5 0 - 0 3 4 6 7 0 6 1 9 7 8 8 0 7 1 3 7 8 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On 6/19/78, it was discovered that the seismic recorder timing marks were out of
03 tolerance. This placed the unit in the Action Statement of Technical Specification
04 3.3.3.3. There was no danger to the health and safety of the public or unit personnel.
05 Three peak recording accelerometers were operable. By transmitting the recording
06 for off-site analysis, the data could have been correlated to properly reflect the
07 actual seismic event. (NP-33-78-90)

08 8 9
09
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
I F E E I N S T R U R Z
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
7 8 0 6 9 0 3 L 1
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
A G Z Z 0 0 0 0 Y N A T 1 0 0 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The troubleshooting of the timing mark problem discovered the 9 volt voltage regulators
11 on the voltage controlled oscillator boards were drifting. Parts were ordered on
12 6/21/78. Work will be performed under Maintenance Work Order IC-78-208. Surveillance
13 Test ST 5034.02, will be revised to include acceptance criteria covering the timing
14 mark tolerance.

15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
G 0 0 0 NA B Surveillance Test Review
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z Z NA NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 Z NA
PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 NA
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z NA

20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
PDR PUBLICITY ISSUED DESCRIPTION
N NA
DVR 78-116 NAME OF PREPARER Ken Aebie PHONE 419-259-5000, Ext. 234
PDR ADOCK 057-346 5 781004