

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	J	M	F	2	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4					
7	12	LICENCE CODE						14	15	LICENCE NUMBER										26	LICENSE TYPE						30	57	CAT	58

CONT

REPORT SOURCE: 0 1 7 8 L 6 0 5 0 0 0 3 6 4 7 0 8 2 4 8 2 3 0 9 2 1 8 2 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0511 on 8/24/82, the 2B auxiliary feedwater pump was declared
0 3 | inoperable when its associated DC control power breaker was inadvertent-
0 4 | ly opened. Tech. Spec. 3.7.1.2 requires the 2B auxiliary feedwater
0 5 | pump to be operable. Tech. Spec. 3.7.1.2 action statement requirements
0 6 | were met. Health/Safety of the public was not affected.
0 7 |
0 8 |

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This event was due to personnel error. In an attempt to remove the
1 1 | 2B containment spray pump from service for scheduled maintenance, the
1 2 | control power breaker for the 2B auxiliary feedwater pump was opened
1 3 | instead. When the control room was called for verification, it was noted
1 4 | immediately that the 2B auxiliary feedwater pump control power

8 9 FACILITY STATUS 1 5 E 29 29 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 OTHER STATUS NA 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 METHOD OF DISCOVERY A 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 DISCOVERY DESCRIPTION MCB Observation by Operator 32

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

AMOUNT OF ACTIVITY (35)
NA

LOCATION OF RELEASE (36)
NA

PERSONNEL EXPOSURES									
NUMBER		TYPE		DESCRIPTION (39)					
1	7	0	0	0	(3)	Z	(38)	NA	

PERSONNEL INJURIES				8209300054 820921	
NUMBER				PDR ADOCK 05000348	
DESCRIPTION				S PDR	
1	0	0	0	(40)	

7		8		9		11		12	
LOSS OF OR DAMAGE TO FACILITY (43)									
TYPE		DESCRIPTION							
1		2		3		4		5	
								N/A	

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

PUBLICATION ISSUED DESCRIPTION (4b) NRC USE ONLY

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

NAME OF PREPARER W. G. Hairston, III

PHONE (205) 899-5156

Cause Description and Corrective Actions

LER 82-036/03L-0

breaker had been opened instead. The breaker was immediately reclosed and the auxiliary feedwater pump returned to service at 0513 on 8/24/82. The individual involved has been counseled about the need for attention to detail while performing his duties.