

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M S G G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 0 9 2 9 8 2 8 1 0 2 8 8 2 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During Non-Nuclear Heatup with the Plant in Operational Mode 3, Control Room

0 3 indication was lost on Plant Chilled Water Auxiliary Building Isolation Valve 1P71F301

0 4 when the valve was cycled during Routine Surveillance Procedure 06-OP-1P71-Q-0001.

0 5 The lost indication prevented recording the closing time of the valve as required by

0 6 T.S.3.6.6.2. This event resulted in no release of radioactivity, damage to the

0 7 facility or effect upon public health and safety. This event is being reported per

0 8 T.S.6.9.1.13.b.

0 9 SYSTEM CODE S D 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE E 15 VALVE SUBCODE D 16

17 LER/RO REPORT NUMBER 8 2 EVENT YEAR 8 2 SEQUENTIAL REPORT NO. 0 8 4 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0

ACTION TAKEN E 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER X 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Upon investigation, it was found that the limit switch for this isolation valve (R. A.

1 1 Hiller, size 2-1/2", air operated gate valve, model 105A-A015) was out of adjustment.

1 2 The limit switch was adjusted and the above Surveillance Test satisfactorily completed

1 3 on September 29, 1982. This LER constitutes a final report.

1 4

1 5 FACILITY STATUS G 28 % POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Test 32

1 6 ACTIVITY CONTENT Z 33 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

2 0 PUBLICITY N 44 DESCRIPTION NA 45

821104011B 811028
PDR ADUCK 05000416
S PDR

NRC USE ONLY

NAME OF PREPARER Original signed by W. H. Chenault

PHONE: _____