

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

November 9, 1982

HTRD-50-518, -520/82-22

U.S. Nuclear Regulatory Commission  
Region II  
ATTN: James P. O'Reilly, Regional Administrator  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:


HARTSVILLE NUCLEAR PLANT UNITS A1 AND A2 - REPORTABLE DEFICIENCY -  
STORAGE AND PREVENTIVE MAINTENANCE PROGRAM DEFICIENCIES - HTRD-50-518,  
-520/82-22

The subject deficiency was initially reported to NRC-OIE, Region II,  
Inspector F. Cantrell on October 7, 1982. In accordance with paragraph  
50.55(e) of 10 CFR Part 50, we are enclosing the final report on  
the subject deficiency.

If you have any questions, please call Jim Domer at FTS 853-2725.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
L. M. Mills, Manager  
Nuclear Licensing

Enclosure

cc: Mr. R. C. DeYoung, Director (Enclosure)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

8211220225 821109  
PDR ADOCK 05000518  
S PDR

OFFICIAL COPY  
I E 27

NOV 12 11:00

RECEIVED  
NRC REGION II  
ATLANTA, GA

ENCLOSURE  
HARTSVILLE NUCLEAR PLANT UNITS A1 AND A2  
STORAGE AND PREVENTIVE MAINTENANCE PROGRAM DEFICIENCIES  
10CFR50.55(e) FINAL REPORT  
CONST AUDIT NO. HT-G-82-13  
HTRD-50-518, -520/82/22

Description of Deficiency

During an audit of the storage and preventive maintenance program by the Site Quality Assurance Audit Unit, five deficiencies were noted. Investigation into the audit has revealed that three of the five deficiencies were written against non-QA items.

The deficiencies on the QA items consisted of improper storage of stainless steel tanks and piping. The tanks were not stored in an upright position and the protective covering had deteriorated. The piping had fallen off its supports and was in contact with the ground and some pipe caps were missing.

Safety Implications

Failure to properly maintain equipment as described in the Quality Assurance Program for the storage and preventive maintenance of mechanical items could result in damage to the equipment and its subsequent failure to perform its safety-related functions, thus having adverse affects on the safe operation of the plant.

Corrective Action

The tanks have been placed in an upright position and moved to inside storage. The piping has been placed on support and pipe caps have been replaced. These two deficiencies have been closed by the Site QA Unit.

A representative from the office of the Manager of Construction visited the project to review site storage conditions. His evaluation was that the overall storage program is in compliance with the Revised OEDC Plan for Storage and Preventive Maintenance for Deferred Nuclear Units.

The responsible craft organizations and the Material Services Unit personnel have been reminded of the importance of the preventive maintenance program. Material Services Unit personnel have been cautioned to be more attentive to storage conditions.

TVA is constantly reviewing the storage and preventive maintenance program to ensure that it complies with the QA requirements imposed by TVA. Basically, this is to ensure that the proper level of protection is afforded to those components which will either be used after the plant restart or sold.

We are now in full compliance and all audit deficiencies have been closed by the auditor.