

LICENSEE EVENT REPORT

EXHIBIT A

| CONTROL BLOCK: | | | | | | | | | | (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|---|--|------------------------------|--|---|--|----|--|----|--|---|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|----|--|
| 01 | | FILC 32010-100000-1003411114 | | | | | | | | | | 5 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | 13 | | 14 | | 15 | | 16 | | 17 | | 18 | | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | 25 | | 26 | | 27 | | 28 | | 29 | | 30 | | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | 37 | | 38 | | 39 | | 40 | | 41 | | 42 | | 43 | | 44 | | 45 | | 46 | | 47 | | 48 | | 49 | | 50 | |
| 01 | | L050-0302710118281110823 | | | | | | | | | | 5 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | 13 | | 14 | | 15 | | 16 | | 17 | | 18 | | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | 25 | | 26 | | 27 | | 28 | | 29 | | 30 | | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | 37 | | 38 | | 39 | | 40 | | 41 | | 42 | | 43 | | 44 | | 45 | | 46 | | 47 | | 48 | | 49 | | 50 | |
| EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| At 0345 during normal operation, the reactor building average air temperature exceeded the 130 degree fahrenheit limit of T.S.3.6.1.5. Additional air handling coolers were started and the containment temperature was decreased to within limit by 0530. There was no effect on public health or safety. This was the ninth time the reactor building temperature exceeded the specified limit. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| SYSTEM CODE SB (11) CAUSE CODE E (12) CAUSE SUBCODE B (13) COMPONENT CODE P I P E X X (14) COMP SUBCODE A (15) VALVE SUBCODE Z (16) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| LER/RO REPORT NUMBER (17) EVENT YEAR (18) SEQUENTIAL REPORT NO. (19) OCCURRENCE CODE (20) REPORT TYPE (21) REVISION NO. (22) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| ACTION TAKEN (23) FUTURE ACTION (24) EFFECT ON PLANT (25) SHUTDOWN METHOD (26) HOURS (27) ATTACHMENT SUBMITTED (28) NPRO-4 FORM SUB. (29) PRIME COMP. SUPPLIER (30) COMPONENT MANUFACTURER (31) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| This event was caused by strain on the instrument air line causing the line to split. Loss of instrument air caused the cooling fans to fail off and the dampers to fail closed, stopping the flow of cooling air in the cooling tower. The line was replaced on October 11, 1982. | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| FACILITY STATUS (32) POWER (33) OTHER STATUS (34) METHOD OF DISCOVERY (35) DISCOVERY DESCRIPTION (36) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| ACTIVITY TAKEN (37) CONTENT (38) AMOUNT OF ACTIVITY (39) LOCATION OF RELEASE (40) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| PERSONNEL EXPOSURES (41) NUMBER (42) TYPE (43) DESCRIPTION (44) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| PERSONNEL INJURIES (45) NUMBER (46) DESCRIPTION (47) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| LOSS OF OR DAMAGE TO FACILITY (48) TYPE (49) DESCRIPTION (50) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| PUBLICATION (51) ISSUED (52) DESCRIPTION (53) | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| NAME OF PREPARER (54) P. G. Hughes PHONE (55) (904) 795-3802 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |