

TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

November 16, 1981 NOV 17 4:31

HTRD-50-518/81-13, -520/81-11

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE NUCLEAR PLANT A - REPORTABLE DEFICIENCY - QA
DOCUMENTATION FOR DRYWELL FRAMED EMBEDMENTS - HTRD-50-518/81-13,
-520/81-11


The subject deficiency was initially reported to NRC-OIE, Region II, Inspectors P. A. Taylor and F. Cantrell on May 20 and May 29, 1981, respectively, as NCR's HNP-142 through 150, 2-HTN, 5-HTN, 6-HTN, and 9-through 12-HTN. In compliance with paragraph 50.55(e) of 10 CFR Part 50, this letter constitutes the fourth interim report on the subject deficiency. TVA is still in the process of evaluating the subject deficiency. A more detailed report of the evaluation will be provided to your office on or before January 20, 1982. TVA has also identified this nonconformance for the Phipps Bend Nuclear Plant. The deficiency was reported to Inspector P. A. Taylor on May 20, 1981 as NCR's 3-PBN, 4-PBN, and 6-PBN. We consider 10 CFR Part 21 applicable to these nonconformances. If you have any questions, please call Jim Domer at FTS 858-2725.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager

Nuclear Regulation and Safety



cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20545

IE27
S
1/0

OFFICE COPY

8111200857 811116
PDR ADOCK 05000518
S PDR