


50-518
519
520
521
553
554

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

81 NOV 18 November 16, 1981
A 8: 04

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - REPORTABLE DEFICIENCIES - HIGH PRESSURE CORE SPRAY COMPONENT WIRING DISCREPANCIES (HNP-A-084, HNP-A-085, HNP-A-086, HNP-A-090, AND PBNP-033) - SUPPLEMENTAL RESPONSE

Please refer to my letter to you dated July 15, 1981 on the subject deficiencies. As discussed with P. A. Taylor on November 5, 1981, TVA could not complete all corrective actions by September 30, 1981. This letter constitutes our supplemental response on these deficiencies.

All hardware corrections were completed by September 30, 1981. Software corrections have been completed by General Electric, and the applicable drawings have been received by TVA. These drawings are currently being reviewed by the affected TVA organizations. Corrective actions, as stated in our final reports are, however, incomplete at this time in that the aforementioned drawings have not been forwarded to the respective sites. We anticipate completion of all stated corrective actions on or before February 5, 1982.

If you have any questions please call Jim Domer at FTS 858-2725.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager

Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8111250293 811116
PDR ADOCK 05000518
S PDR

OFFICIAL COPY

FE 22

1227