

CONTROL BLOCK:

						1
--	--	--	--	--	--	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1
---	---

 N J S G S 2

2

 o o - 0 0 0 0 0 0 - 0 0

3

 4 1 1 1 1

4

--	--

5

7 8 9 14 15 25 26 30 57 CAT 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

0 1
7 8

REPORT SOURCE L 6 0 5 0 0 0 3 1 1 7 1 0 0 6 8 1 8 1 1 1 8 8 1 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On October 6, 1981 it was discovered that a Penetration Canister requiring fire
0 3 | barrier protection on Design Change Package (DCP) 2EC-1145 had not been wrapped.
0 4 | This discovery prompted a 100% audit to the safe shutdown and interaction analysis,
0 5 | which includes vital cable and cable tray fire wrapping and fire barrier installation.
0 6 | That audit revealed four additional open items on the DCP.
0 7 |
0 8 |

SYSTEM CODE [0][9] (7)(8)		CAUSE CODE [E][E] (11) (9)(10)		CAUSE SUBCODE [A] (12) (11)		COMPONENT CODE [E][L][E][C][O][N] (14) (12)(13)(14)(15)(16)(17)(18)				COMP. SUBCODE [Z] (15) (19)(20)		VALVE SUBCODE [Z] (16) (21)(22)	
(17) LER/RO REPORT NUMBER		EVENT YEAR [8][1] (21)(22)		SEQUENTIAL REPORT NO. [] (23)		[1][0][4] (24)(25)(26)		OCCURRENCE CODE [] (27)		REPORT TYPE [X] (28)(29)		REVISION NO. [2] (30)(31)	
ACTION TAKEN [X] (18) (33)		FUTURE ACTION [Z] (19) (34)		EFFECT ON PLANT [Z] (20) (35)		SHUTDOWN METHOD [Z] (21) (36)		HOURS [0][0][0][0] (22) (37)(38)(39)(40)		ATTACHMENT SUBMITTED [Y] (23) (41)		NPRD-4 FORM SUB. [N] (24) (42)	
PRIME COMP. SUPPLIER [L] (25) (43)		COMPONENT MANUFACTURER [Z][9][9][9] (26) (44)(45)(46)(47)											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Personnel error. The open items were either omitted from the DCP, or partially or
1 1 | incorrectly protected. Fire watches were posted within one hour. A walkdown of the
1 2 | DCP was completed. Subsequently, all required wrappings were properly accomplished.
1 3 | No additional items at variance were found. We are now in full compliance with our
1 4 | safe shutdown and interaction analysis. (81-85)

FACILITY STATUS		% POWER			OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION						
1	5	D	28	0	0	0	29	NA	30	C	31	Special Inspection	32
7	8	9	10	11	12	13	14	15	16	17	18	19	20

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z 33 Z 34 NA

7 8 9 10 11 44

NA LOCATION OF RELEASE (36)

45

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	40 NA

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	

PUBLICITY
 ISSUED DESCRIPTION (45)
 2 0 N 44 NA
 7 8 9 10 68 69 80

NAME OF PREPARER Frank Dickey

PHONE: 609-935-0998