

USNRO REGION II
ATLANTA, GEORGIA

81 NOV 30 AID: 40



Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

Re: St. Lucie Unit 1
Docket No. 50-335
Notification of Unusual Event

On November 25, 1981, a station service transformer failed taking four Motor Control Centers (MCC) out of service. These MCC's serviced various equipment in the fuel handling building, one diesel generator building, and the reactor area. The reactor was shutdown for refueling and overhaul at the time. The shutdown cooling systems remained in service. All plant parameters remained normal and there was no concern for radiological releases. No personnel injuries resulted from the incident.

The Nuclear Plant Supervisor on duty at St. Lucie declared the incident an Unusual Event and notified the Nuclear Regulatory Commission, State Warning Point in Tallahassee, and the FPL Emergency Control Officer (ECO).

The purpose of this letter is to notify you of an Unusual Event in accordance with Emergency Plan Implementing Procedure 1101.

Very truly yours,

A handwritten signature in cursive script, appearing to read "J. W. Williams, Jr.".

J. W. Williams, Jr.
Director, Nuclear Energy

JWW/JJM/ras

cc: Harold F. Reys, Esquire
Robert E. Uhrig
Mr. Robert A. Hawfield, Jr.
Bureau Chief
Bureau of Disaster Preparedness
1720 South Gadsden Street
Tallahassee, Florida 32301

8112070436 811130
PDR ADOCK 05000335
S PDR

OFFICIAL COPY

IE 22
S10