



Wisconsin
Electric
POWER COMPANY

231 W. Michigan, P.O. Box 2046, Milwaukee, WI 53201

(414) 221-2345

VPNPD-93-041

NRC-93-020

February 19, 1993

Document Control Desk
U.S. NUCLEAR REGULATORY COMMISSION
Mail Station P1-137
Washington, DC 20555

Gentlemen:

DOCKET 50-301

LICENSEE EVENT REPORT 92-006-01

INADVERTENT ESF ACTUATION AS A RESULT OF AS-BUILT WIRE TRACING
POINT BEACH NUCLEAR PLANT, UNIT 2

Enclosed is Licensee Event Report 92-006-01 for Point Beach Nuclear Plant, Unit 2. This supplemental report is being submitted in order to clarify certain portions of the report. This report describes the inadvertent actuation of a non-safeguards equipment lockout. The trip of this lockout is believed to have occurred when a "B" train safety injection relay was inadvertently bumped during as-built wire tracing in the Unit 2 safeguards racks.

Please contact us if there are any questions.

Sincerely,

Bob Link
Vice President
Nuclear Power

FDP/jg

Enclosure

cc: NRC Regional Administrator, Region III
NRC Resident Inspector

010030

9303020303 930219
PDR ADDCK 05000301
S PDR

A subsidiary of Wisconsin Energy Corporation

JE22