



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401-1927
Telephone (612) 330-5500

April 27, 1993

Report Required by
10 CFR Part 50, Section 50.73

US Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Failure of Emergency Service Water Check
Valves to Seat Caused by an Accumulation of Silt

The supplemental Licensee Event Report for this occurrence is attached. This report contains the following new NRC commitment.

An evaluation will be performed to determine the feasibility of replacing check valves ESW-13 and ESW-14 with valves less susceptible to failure due to silt accumulation.

Please contact Marv Engen, Sr Licensing Engineer, at (612) 295-1291 if you require further information.

Roger O Anderson
Director
Licensing and Management Issues

c: Regional Administrator - III, NRC
NRR Project Manager, NRC
Sr Resident Inspector, NRC
State of Minnesota
Attn: Kris Sanda

Attachment

040104

9305050114 930427
PDR ADOCK 05000263
S PDR

IEP
11