

No. 2-81-05/3L

This LER concerns failure of a torus vent valve to close. Applicable

Tech. Specs are 3.7.D.2 and 4.7.D.2.

## U. S. NUCLEAR REGULATORY COMMISSION

**LICENSEE EVENT REPORT**[illegible]

S

8102040 471