

No. 2-81-07/3L

This LER concerns failure to adjust average power range monitor (APRM) gains during control rod and recirculation flow adjustments. Applicable Technical Specifications are 2.1.A and 2.1.A Bases.

LICENSEE EVENT REPORT

810 2120 042 S