

No. 3-81-02/3L

This LER concerns failure of a HPCI turbine exhaust drain isolation valve to stroke properly during surveillance testing. Applicable Technical Specification is 3.7.D.

8102170107