



Carolina Power & Light Company

April 15, 1982

CQAD 82-665

FILE: SHN-2/18  
Item 71

62 APR 19 82 40

Mr. James P. O'Reilly  
United States Nuclear  
Regulatory Commission  
Region II  
101 Marietta St., N.W.  
Atlanta, Georgia



SHEARON HARRIS NUCLEAR POWER PLANT UNIT 1  
DOCKET NO. 50-400  
DEFICIENCIES IN WELDED STUDS ON EMBEDDED STRIP PLATES

Dear Mr. O'Reilly:

Attached is Addendum No. 1 to the final 10CFR50.55(e) report issued to the NRC on March 19, 1982, for the above subject deficiency. This addendum describes an additional occurrence and the associated required corrective action. Please attach this addendum to the March 19, 1982, final report.

If you have any questions regarding this matter, please contact me.

Very truly yours,

N. J. Chiang-Manager  
Engineering & Construction  
Quality Assurance/Quality Control

TH:pfb

Attachment

cc: Mr. H. R. Banks	Mr. P. W. Howe
Mr. D. L. Bensinger (HI/A-2D)	Mr. L. I. Loflin
Mr. A. B. Cutter	Mr. A. M. Lucas
Mr. C. R. Dietz	Mr. M. A. McDuffie
Dr. T. S. Elleman	Mr. C. H. Moseley, Jr.
Mr. G. L. Forehand (2)	Mr. R. M. Parsons
Mr. T. L. Harrington	Mr. Sheldon D. Smith
Mr. E. Harris	Mr. R. B. Starkey, Jr.
Mr. S. Hinnant	File

8204280302

OFFICIAL COPY

1027  
3/1

SHEARON HARRIS NUCLEAR POWER PLANT

UNIT NO. 1

DEFICIENCIES IN WELDED STUDS  
ON EMBEDDED STRIP PLATES

ADDENDUM NO. 1 TO FINAL REPORT  
ISSUED MARCH 19, 1982

April 15, 1982

On April 5, 1982, N. J. Chiangi notified the NRC (Mr. C. Julian) that another DDR had been written identifying the same type problem reported in a final 10CFR50.55(e) report dated March 19, 1982. During the discussion, it was agreed that since this additional DDR (No. 862) dealt with the same type deficiency, material and corrective action, it was not necessary for CP&L to provide an additional report. CP&L has provided the same corrective action for DDR No. 862 as indicated in the final report dated March 19, 1982.