

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE: 912-367-7781

LER No.: 50-366/1982-017
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket No.: 50-366

Narrative Report
for LER 50-366/1982-017.

On February 11, 1982, while the unit was at 92% power, operators reported Drywell/Torus Temperature Recorder, 2T47-R627, was inop during shift turn-over review. The redundant recorder was operable. Tech Specs Section 3.3.6.4-1 requires 2 monitors operable. Plant operation nor public health was affected. This is a non-repetitive event.

The cause of the event was failure of the input selector board of the recorder. The board was replaced and the recorder recalibrated. The recorder was put back into service.