

LER NO.: 50-366/1982-027
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket No.: 50-366

Narrative Report
for LER No. 50-366/1982-027.

While the plant was in refuel with secondary containment not in effect, HNP-2-3553, Reactor Building Exhaust Vent Radiation Monitor Functional Test and Calibration, exceeded the surveillance interval by 2 days. Tech Specs Section 4.3.2-1 requires functional test monthly: this was not met. Neither plant operation nor public health and safety was affected by this event. This event is repetitive as last reported on Reportable Occurrence Report No. 50-366/1981-050.

The cause of this event has been attributed to personnel error. Personnel failed to schedule work required. The surveillance procedures which was not performed within the allowable time limit was done immediately when it was discovered it had been overlooked. The personnel responsible have been counseled as to the importance of scheduling all required surveillance.