

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The 2G bus was deenergized when breaker 2-DG15 opened. All events considered as possible causes were investigated. Instrumentation indicators and recordings were not sufficient to prove conclusively the actual cause. One of the relays which trips the breaker does not utilize targets in the present design. The addition of targets to this relay will be evaluated as part of a design modification to allow a more detailed analysis of the

(Attached)

NAME OF PREPARED W. G. Hairston, III

PHONE: (205) 899-5156

8204280557

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

event should a similar incident occur in the future. Following a thorough inspection of the breaker and circuitry, the 2-DG15 breaker was closed restoring the "B" train electrical circuit at 1509 on 2/26/82.