



Docket No. 50-346

License No. NPF-3

Serial No. 1-260

April 14, 1982

RICHARD P. CROUSE
Vice President
Nuclear
(419) 259-5221

Mr. James G. Keppler, Director
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

This is Toledo Edison's response to Inspection Report 50-346/82-04 (Log No. 1-592) which pointed out one item of non-compliance concerning the activities of Davis-Besse Nuclear Power Station Unit No. 1. This item specifically addressed the failure of seven licensed operators to complete assigned required reading.

The training staff at Davis-Besse has verified that licensed operators have since completed the assigned required reading in question. In addition, the training department has initiated the practice of sending a monthly memorandum to any licensed operator who has not completed his assigned required reading for the previous month.

Inspection Report 50-346/82-04 also referenced an unresolved item concerning the storage of operator training records which are awaiting microfilming in non-fire rated cabinets. These records are now being stored in a fire-rated cabinet.

Very truly yours,

R P Crouse

RPC:RFP:lab

cc: DB-1 NRC Resident Inspector

a/1

8204300373

APR 19 1982