

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6
---	---	---	---	---	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1
---	---

N	Y	J	A	F	1
---	---	---	---	---	---

2	0	0	-	0	0	0	0	-	0	0	0
---	---	---	---	---	---	---	---	---	---	---	---

3	4	1	1	1	1
---	---	---	---	---	---

4					
---	--	--	--	--	--

5

7 8 9 14 15 25 26 30 57 CAT 58CON'T

0	1
---	---

 REPORT SOURCE

L	6	0	5	0	0	0	3	3	3
---	---	---	---	---	---	---	---	---	---

 DOCKET NUMBER

7	0	3	2	7	8	2
---	---	---	---	---	---	---

 EVENT DATE

8	0	4	2	0	8	2
---	---	---	---	---	---	---

 REPORT DATE
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2
---	---

 During normal operation, personnel noted a sudden increase in indicated contain-

0	3
---	---

 ment oxygen concentration on oxygen analyzer 'A'. The analyzer read approximately

0	4
---	---

 8 percent compared to a TS 3.7.A.6 limit of 4 percent. Analyzer 'B' was out of

0	5
---	---

 service at the time. Utilizing portable equipment, samples were taken and oxygen

0	6
---	---

 concentration of greater than 4 percent was confirmed. No significant hazard

0	7
---	---

 existed.

0	8
---	---

7 8 9 80

0	9
---	---

I	E
---	---

 (11)

E

 (12)

E

 (13)

I	N	S	T	R	U
---	---	---	---	---	---

 (14)

X

 (15)

Z

 (16)
7 8 9 10 11 12 13 18 19 20
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
(17) LER/RO REPORT NUMBER

8	2
---	---

--

0	1	5
---	---	---

--

0	3
---	---

L

--

0

21 22 23 24 26 27 28 29 30 31 32
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS (22) ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

A

 (18)

Z

 (19)

Z

 (20)

Z

 (21)

0	0	0	0
---	---	---	---

N

 (23)

Y

 (24)

A

 (25)

B	1	3	5
---	---	---	---

 (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0
---	---

 Investigation revealed that leakage existed on the inlet side of the sample

1	1
---	---

 system for the analyzer. Correction of the leaks, recalibration of the monitor

1	2
---	---

 and purge of containment with nitrogen corrected the problem. Oxygen concentra-

1	3
---	---

 tion was restored to within the TS limits within 24 hours.

1	4
---	---

7 8 9 80

1	5
---	---

E

 (28)

0	6	3
---	---	---

 (29)

NA

 (30)

A

 (31) Operator Observation (32)
7 8 9 10 12 13 44 45 46 80
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1	6
---	---

Z

 (33)

Z

 (34)

NA

 (35)

NA

 (36)
7 8 9 10 11 44 45 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)

1	7
---	---

0	0	0
---	---	---

 (37)

Z

 (38)

NA

 (39)
7 8 9 11 12 13 80
PERSONNEL INJURIES NUMBER DESCRIPTION (41)

1	8
---	---

0	0	0
---	---	---

 (40)

NA

 (41)
7 8 9 11 12 80
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)

1	9
---	---

Z

 (42)

NA

 (43)
7 8 9 10 80
PUBLICITY ISSUED DESCRIPTION (45)

2	0
---	---

N

 (44)

NA

 (45)
7 8 9 10 80
8205040522 820420
PDR ADOCK 05000333 PDR
W. Verne Childs
(315) 342-3840 X207
NRC USE ONLY
58 59 80 90