

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

590 917-926

LER NO. 82-15/3L  
DOCKET NO. 50-317  
LICENSE NO. DPR-53  
EVENT DATE 04-07-82  
REPORT DATE 04-23-82  
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The cause of this incident was failure on the part of the Control Room Operator and technician to realize the commonality of the reference leg for PT-102C and LT-110Y even though it was indicated on the system print. This incident has been discussed with the personnel involved. Additionally, all I&C technicians and licensed operators will be informed of the details of this event.