



**LOUISIANA  
POWER & LIGHT**


142 DELARONDE STREET  
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 30, 1982

G. D. McLENDON  
Senior Vice President

W3K-82-0255  
Q-3-A35.07.40

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 40  
Second Interim Report  
"ITE-Gould Starter Coil Failure in Containment Cooling Fans"

Reference: 1) LP&L letter W3K-81-0412 to NRC dated November 17, 1981  
2) Telecon - L. L. Bass (LP&L) to B. Crossman (NRC) on 4/27/82

Dear Mr. Collins:

In reference 1, LP&L committed to provide a final report on SCD #40 by April 30, 1982. Since the first interim report was submitted, the remaining six coils have been received and are now scheduled for installation during the first week of May.

Based on the above information, a final report will be submitted on or before May 31, 1982.

Very truly yours,

*G. D. McLendon*

GDMcL/LLB/grf

- cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555
- 2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555



8205070231 820430  
PDR ADOCK 05000382  
S PDR

IE 27  
S/0