



DESIGNATED ORIGINAL

Certified By M.A. Perkins 5/6/82

Public Service Electric and Gas Company P.O. Box E Hancock Bridge, New Jersey 08038

Salem Generating Station

February 11, 1982

Mr. R. C. Haynes
Regional Administrator
USNRC
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Haynes:

REPORTABLE OCCURRENCE 82-07/01P
SALEM NO. 1 UNIT LER

REPORTABLE OCCURRENCE 82-07/01P
SALEM NO. 2 UNIT LER

This letter is to confirm our verbal report to the NRC Resident Inspector at 1030 hours, February 11, 1982, advising of a potential reportable occurrence in accordance with Technical Specification 6.9.1.8.i.

During an engineering seismic analysis of the Auxiliary Feed Water System, the discovery was made that two check valves, with associated piping, were not seismically protected, and their failure could compromise the emergency operation of the system.

An investigation is in progress and a detailed report will be submitted pursuant to Technical Specification 6.9.1.

Sincerely yours,

H. J. Midura
General Manager -
Salem Operations

8205140198 820211
PDR ADOCK 05000272
S PDR

FD:nad

CC: General Manager - Nuclear Production
General Manager - Quality Assurance

IE29
5/10