

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D I C C 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 6 7 0 4 1 2 8 2 8 0 5 1 2 8 2 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2 DURING NORMAL OPERATION, WHILE CONDUCTING A SURVEILLANCE TEST ON THE CONTROL ROOM
0 3 EMERGENCY VENTILATION SYSTEM, AIR FLOW WAS FOUND TO BE 7370 CFM FOR 2-ACRF-1. T.S.
0 4 4.7.5.1.C.4 DESIGNATES A MAXIMUM ALLOWABLE FLOW OF 6600 CFM. DAMPERS WERE REPOSITIONED
0 5 SUCH THAT AIR FLOW WITHIN THE T.S. LIMIT WAS OBTAINED.
0 6
0 7
0 8

0 9 SYSTEM CODE S G 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE F I L T E R 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

17 LER/RO REPORT NUMBER 8 2 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

18 ACTION TAKEN E 19 FUTURE ACTION X 20 EFFECT ON PLANT Z 21 SHUTDOWN METHOD Z 22 HOURS 0 0 0 0 23 ATTACHMENT SUBMITTED Y 24 NPRD-4 FORM SUB. N 25 PRIME COMP. SUPPLIER Z 26 COMPONENT MANUFACTURER Z 9 9 9 9 27

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0 INVESTIGATION REVEALED THAT THE SYSTEM PREFILTERS WERE CHANGED IN AUG-1981. THE NEW
1 1 PREFILTERS MAY HAVE CAUSED AN INCREASE IN AIR FLOW. IN AUG-1981, THERE WAS NO PROCE-
1 2 DURAL REQUIREMENT TO VERIFY THE AIR FLOW AFTER PREFILTER CHANGES. TO PREVENT REOCCUR-
1 3 RENCE, A LETTER HAS BEEN SENT TO ALL DEPARTMENTS AS A REMINDER THAT FLOW MEASUREMENTS
1 4 SHOULD BE PERFORMED AFTER ALL MAJOR WORK ON T.S. VENTILATION SYSTEM.(SEE SUPPLEMENT)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 5 FACILITY STATUS E 28 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 SURVEILLANCE TEST 32 DISCOVERY DESCRIPTION
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 6 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NRC USE ONLY

8205180362

J. L. RISCHLING

PHONE: 616-465-5901

GPO 917-926

SUPPLEMENT TO CAUSE DESCRIPTION

THE INVESTIGATION DID NOT REVEAL THAT ANY MAJOR REPAIR WORK SUCH AS FAN MAINTENANCE, DAMPER ADJUSTMENT, ETC., WAS PERFORMED ON THE CONTROL ROOM EMERGENCY VENTILATION SYSTEM. HOWEVER, IT WAS DISCOVERED THAT ON AUGUST 10, 1981, A PERFORMANCE ENGINEER EXAMINED THE PREFILTERS FOR THE CONTROL ROOM EMERGENCY VENTILATION SYSTEM AS HE WAS REVISING THE APPLICABLE SURVEILLANCE TEST PROCEDURE. NOTICING THAT THE PREFILTERS WERE VERY DIRTY, HE INITIATED A JOB ORDER TO CHANGE THE PREFILTERS. THE PREFILTERS WERE CHANGED ON AUGUST 13, 1981. NO RETEST WAS CONDUCTED AT THAT TIME SINCE THERE WAS NO PROCEDURAL REQUIREMENT FOR A FLOW VERIFICATION FOLLOWING PREFILTER REPLACEMENT. A FLOW TEST WAS CONDUCTED ON APRIL 12, 1982, AS PART OF THE REQUIRED 18-MONTH SURVEILLANCE. TO PREVENT REOCCURRENCE: A LETTER HAS BEEN SENT TO ALL DEPARTMENTS TO INFORM THEM THAT A FLOW VERIFICATION MUST BE PERFORMED EACH TIME A MAJOR CHANGE IS MADE ON ANY T.S. REQUIRED VENTILATION SYSTEM; THE APPROPRIATE SURVEILLANCE TEST PROCEDURE HAS ALSO BEEN MODIFIED TO INCLUDE A STATEMENT TO PERFORM A FLOW VERIFICATION WHEN THE PREFILTERS ARE CHANGED.