

CONTROL BLOCK:

| | | | | | | |
|--|--|--|--|--|--|--|
| | | | | | | |
|--|--|--|--|--|--|--|

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

| | | | | | | | | | | | | | | | | | | | | | | | |
|--------------|----|----------------------|----|-------------------|-----------------|-----------------|----|--------------------------------|----|----|-------------------------------|----------------------|------------------|----|----------------------|--|------------------------|--------------------|--|----|--------------------|--|----|
| 09 | | SYSTEM CODE Z Z | | 11 | CAUSE CODE A | | 12 | CAUSE SUBCODE X | | 13 | COMPONENT CODE Z Z Z Z Z Z | | | | | | 14 | COMP. SUBCODE Z | | 15 | VALVE SUBCODE Z | | 16 |
| 7 | 8 | 9 | 10 | | 11 | | 12 | | 13 | | | | | | 18 | | 19 | | | 20 | | | |
| 17 | | LER/RO REPORT NUMBER | | EVENT YEAR 8 2 | | 21 | 22 | SEQUENTIAL REPORT NO. 0 4 4 | | 24 | 26 | OCCURRENCE CODE / | | 27 | REPORT TYPE T | | 30 | REVISION NO. 0 | | 32 | | | |
| ACTION TAKEN | | FUTURE ACTION | | EFFECT ON PLANT | | SHUTDOWN METHOD | | HOURS | | 22 | ATTACHMENT SUBMITTED | | NPRD-4 FORM SUB. | | PRIME COMP. SUPPLIER | | COMPONENT MANUFACTURER | | | | | | |
| H | | Z | | Z | | Z | | 0 0 0 0 | | 22 | Y | | N | | Z | | Z 9 9 9 | | | | | | |
| 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | | | | | | | | | |

| | |
|---|---|
| 1 | 3 |
|---|---|

 techniques.

| | | |
|---|---|--|
| 1 | 4 | |
|---|---|--|

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)

1 5 G 0 0 0 NA B Security Investigation

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z (33) Z (34) NA

7 8 9 10 11 44

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA

45 46

| PERSONNEL EXPOSURES | | | | | | | | | |
|---------------------|---|---|------|-------------|----------------|--|--|--|--|
| NUMBER | | | TYPE | DESCRIPTION | | | | | |
| 1 | 7 | 0 | 0 | 0 | (37) Z (38) NA | | | | |

| PERSONNEL INJURIES | | NUMBER | | DESCRIPTION | |
|--------------------|---|--------|---|-------------|----|
| 1 | 8 | 0 | 0 | 0 | NA |

| 1 | | 9 | | Z | | 42 | | 43 | |
|-------------------------------|--|------|--|-------------|--|----|--|----|--|
| 7 | | 8 | | 9 | | 10 | | 11 | |
| LOSS OF OR DAMAGE TO FACILITY | | TYPE | | DESCRIPTION | | | | | |
| | | | | | | NA | | | |

PUBLICITY ISSUED DESCRIPTION (45) NA NRC USE ONLY

NRC USE ONLY

NAME OF PREPARER T. C. Wilkes

PHONE: 367-7781 ext 102

LER #: 50-321/1982-044
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-321

Narrative Report
for LER 50-321/1982-044

On 4/26/82 an unloaded .38 caliber revolver and a box of ammunition for this weapon was discovered under the driver's seat of a contractor's vehicle prior to its exiting the protected area. This resulted from a security officer failing to adequately search the interior of the vehicle prior to its entry into the protected area; however, the vehicle had been escorted to its destination inside the protected area by a security officer, the steering wheel disabled, the front doors locked and the keys retained by Security. The driver had authorized unescorted access to the protected area, but did not have access to the weapon while inside the protected area due to Security maintaining key to locked vehicle. The security officers were briefed on proper searching procedures on 4/27/82 and 4/28/82, and this briefing was formally documented. All officers that were not on duty are being briefed upon their return to duty. The contractor has been restricted from the plant site pending further investigation. This event was reported on Deviation Report 1-82-69.

This is a non-repetitive event, and there was no effect upon the public health and safety due to this event.