

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01
WIKNP1200-00000-0034111145

LICENSEE CODE

LICENSE NUMBER

LICENSE TYPE

CAT 58

CON'T

01
L605000305703098280407829

REPORT SOURCE

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 During quarterly surveillance testing of service water pumps, 1A2 service water pump
03 failed to start on demand. One service water pump may be out of service for up to
04 48 hours per T.S.3.3.d.2.A.; this is reportable per T.S.6.9.2.b.(2) as operation
05 permitted by an LCO. The remaining service water pumps were available, therefore,
06 there was no effect on public safety or plant operation.
07
08

09
WA11
E12
A13
CKTBRK14
A15
Z16

17
82
005
03
X
1

A18
Z19
Z20
Z21
0000
N23
Y24
A25
X999926

10 The circuit breaker failed to close by remote auto or manual initiation, due to a
11 failed open closing coil. The coil was replaced, tested satisfactory, and the
12 service water pump returned to service within T.S. time limits. This closing
13 coil failure is considered spurious (non-recurrent) and requires no further
14 corrective action.

15
E28
10029
NA
B31
Surveillance Testing

16
Z33
Z34
NA
NA

17
00037
Z38
NA

18
00040
NA

19
Z42
NA

20
N44
NA

8205180608

NAME OF PREPARER C. S. Smoker

PHONE: (414) 388-2560 Ext. 340