

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE: 912-367-7781

LER No.: 50-321/1982-009.
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket No.: 50-321

Narrative Report
for LER 50-321/1982-009.

While the plant was in startup mode at 10 MWt, 1T48-R622B, Torus Water Level Indicator, was found to be indicating abnormal level. Tech Specs Table 3.2-11 item 8 requires two operable channels. Redundant indicator 1T48-R622A was operable. Plant operation was placed in a 30 day LCO as a result of this event. The health and safety of the public was not affected. This is a repetitive event as last reported on Reportable Occurrence Report No. 50-321/1981-071.

The event was caused by loss of water in the reference leg of transmitter 1T48-N010B which feeds 1T48-R622B. The reference leg was refilled and the instruments were returned to service.