

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
<div> <div>01</div> <div>N C M G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4</div> <div>7 8 9 14 15 25 26 30 37 38</div> </div> <div>LICENSE CODE</div> <div>LICENSE NUMBER</div> <div>LICENSE TYPE</div> <div>CAT 58</div>										<div> <div>01</div> <div>L 9 0 5 0 0 0 3 6 9 7 0 4 0 2 8 2 8 0 5 0 6 8 2 9</div> <div>7 8 9 14 15 25 26 30 37 38</div> </div> <div>REPORT SOURCE</div> <div>DOCKET NUMBER</div> <div>EVENT DATE</div> <div>REPORT DATE</div>									
<div>02</div> <div>While in mode 1, investigation of PORV and pressurizer code safety discharge line</div>																			
<div>03</div> <div>high temperature alarms revealed indications of leakage for PORV NC-34 (the</div>																			
<div>04</div> <div>faulty valve was identified by closing PORV block valves and observing the effect</div>																			
<div>05</div> <div>on discharge line temperature indication). The valve was declared inoperable per</div>																			
<div>06</div> <div>T.S.3.4.5 which is reportable per T.S.6.9.1.13(b) and similar to previous RO#369/</div>																			
<div>07</div> <div>82-04. Since the two remaining PORVs are operable (as well as 3 pressurizer code</div>																			
<div>08</div> <div>safety valves), the health and safety of the public are unaffected.</div>																			
<div>09</div> <div> <div>C B 11</div> <div>E 12</div> <div>X 13</div> <div>V A L V E X 14</div> <div>F 15</div> <div>B 16</div> <div>17</div> <div>8 2</div> <div>0 2 9</div> <div>0 3</div> <div>L</div> <div>0</div> <div>X 18</div> <div>D 19</div> <div>Z 20</div> <div>Z 21</div> <div>0 0 0 0</div> <div>N 23</div> <div>N 24</div> <div>L 25</div> <div>C 6 0 0 0</div> <div>26</div> </div> <div>SYSTEM CODE</div> <div>CAUSE CODE</div> <div>CAUSE SUBCODE</div> <div>COMPONENT CODE</div> <div>COMP. SUBCODE</div> <div>VALVE SUBCODE</div> <div>LER/RO REPORT NUMBER</div> <div>EVENT YEAR</div> <div>SEQUENTIAL REPORT NO.</div> <div>OCCURRENCE CODE</div> <div>REPORT TYPE</div> <div>REVISION NO.</div> <div>ACTION TAKEN</div> <div>FUTURE ACTION</div> <div>EFFECT ON PLANT</div> <div>SHUTDOWN METHOD</div> <div>HOURS</div> <div>ATTACHMENT SUBMITTED</div> <div>NPRO-4 FORM SUB.</div> <div>PRIME COMP. SUPPLIER</div> <div>COMPONENT MANUFACTURER</div>																			
<div>10</div> <div>Due to continued plant operation, inspection of the valve to determine the exact</div>																			
<div>11</div> <div>nature of component failure has not yet been possible. Per Technical Specifica-</div>																			
<div>12</div> <div>tions, the PORV was isolated by closing and de-energizing its block valve (NC-</div>																			
<div>13</div> <div>33). The PORV will be repaired during the June 18 to July 14 outage.</div>																			
<div>14</div> <div></div>																			
<div>15</div> <div> <div>B 28</div> <div>0 5 0 29</div> <div>N/A</div> <div>A 31</div> <div>High temperature alarms</div> <div>32</div> </div> <div>FACILITY STATUS</div> <div>% POWER</div> <div>OTHER STATUS</div> <div>METHOD OF DISCOVERY</div> <div>DISCOVERY DESCRIPTION</div>																			
<div>16</div> <div> <div>Z 33</div> <div>Z 34</div> <div>N/A</div> <div>N/A</div> <div>35</div> <div>36</div> </div> <div>ACTIVITY CONTENT</div> <div>RELEASED OF RELEASE</div> <div>AMOUNT OF ACTIVITY</div> <div>LOCATION OF RELEASE</div>																			
<div>17</div> <div> <div>0 0 0 37</div> <div>Z 38</div> <div>N/A</div> <div>39</div> </div> <div>PERSONNEL EXPOSURES</div> <div>NUMBER</div> <div>TYPE</div> <div>DESCRIPTION</div>																			
<div>18</div> <div> <div>0 0 0 40</div> <div>N/A</div> <div>41</div> </div> <div>PERSONNEL INJURIES</div> <div>NUMBER</div> <div>DESCRIPTION</div>																			
<div>19</div> <div> <div>Z 42</div> <div>N/A</div> <div>43</div> </div> <div>LOSS OF OR DAMAGE TO FACILITY</div> <div>TYPE</div> <div>DESCRIPTION</div>																			
<div>20</div> <div> <div>N 44</div> <div>N/A</div> <div>45</div> </div> <div>PUBLICITY</div> <div>ISSUED</div> <div>DESCRIPTION</div>																			
<div>21</div> <div></div>																			

8205210399 820506
PDR ADCK 05000369
S PDR

Nardoci

PHONE: (704) 373-7432