

BOSTON EDISON COMPANY

Certified By malPROMPT REPORTABLE OCCURRENCETELECOPY MESSAGETO: (215) 337-5324
Telephone Number

DATE/TIME: 5/13/82 / 1200

TO: Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406FROM: Pilgrim Nuclear Power Sta.
RFD#1, Rocky Hill Road
Plymouth, MA 02360Docket Number 50-293
License DPR-35

Assigned LER Number 82-014/01X-0

Reported per T.S. Section 6.9.B.1.b.

Event Description: On May 6, 1982 at approximately 1133 hours a sliding fire door on the 23 foot elevation of the 'B' Switchgear room (Door #90) was found to be inoperable. It's fusible link was missing. The fire watch was not established within one hour as required by T.S. Section 3.12.F.

Cause and Corrective Action: A fire watch was established after being notified of door's status at approximately 1415 hours and the door returned to service by 1445 the same day. Communication of the fire door's status to security for the assignment of the necessary fire patrol was tardy. The reason for this delay is being investigated.

Facility Status:

99 % Thermal MW

c) Routine Startup _____
d) Routine Shutdown _____
e) Steady State X _____
f) Load Changing _____

g) Shutdown _____
h) Refueling _____
i) Other _____
j) Not Applicable _____

A written followup report will be sent within two weeks.

NRC Person Notified J. R. Johnson

Prepared by M. T. McLoughlin

Mail (2) copies to:

Director
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

cc: Standard LER Distribution

8205240550 820513
PDR ADDCK 05000293
PDR
S

IE 29
5/10