

REPORT
SOURCE

L

60

61

DOCKET NUMBER

68

EVENT DATE

69

REPORT DATE

74

75

80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

At 1300 on 3/05/82 the containment air lock was declared inoperable when the cam lock on the outer door was found broken. Tech. Spec. 3.6.1.3 requires this air lock to be operable. Tech. Spec. 3.6.1.3 action statement requirements were met. Health/safety of the public was not affected.

SYSTEM
CODE

S A

9

10

CAUSE
CODE

E

11

12

CAUSE
SUBCODE

B

12

13

COMPONENT CODE

P E N E T R

13

14

COMP
SUBCODE

A

19

20

VALVE
SUBCODE

Z

20

21

LER RD
REPORT
NUMBER

17

21

22

EVENT YEAR

8 2

23

24

SEQUENTIAL
REPORT NO.

0 1 1

25

26

OCCURRENCE
CODE

0 3

27

28

REPORT
TYPE

L

30

31

REVISION
NO.

0

32

33

ACTION FUTURE

TAKEN ACTION

A Z

33

34

EFFECT
ON PLANT

Z

35

36

SHUTDOWN
METHOD

Z

37

38

HOURS

0 0 0 0

39

40

ATTACHMENT
SUBMITTED

N

41

42

NPRD-4
FORM SUB

N

43

44

PRIME COMP.
SUPPLIER

A

45

46

COMPONENT
MANUFACTURER

C 3 1 0

47

48

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

This event was caused by a broken cam lock. The broken cam lock on the outer door was repaired. Following the satisfactory completion of FNP-0-STP-607.0 (Containment Airlocks Interlock Test) the containment airlock was declared operable at 2300 on 3/05/82.

FACILITY
STATUS

C

28

29

% POWER

0 0 0

30

31

OTHER STATUS

NA

44

45

METHOD OF
DISCOVERY

A

31

46

DISCOVERY DESCRIPTION

Operational Event

80

81

ACTIVITY CONTENT

RELEASED OF RELEASE

Z

33

34

AMOUNT OF ACTIVITY

NA

44

45

LOCATION OF RELEASE

NA

80

81

PERSONNEL EXPOSURES

NUMBER TYPE DESCRIPTION

0 0 0 Z

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

8204160436 820402
PDR ADDCK 05000348
S PDR

irston, III

PHONE (205) 899-5156