

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

March 31, 1982

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Re: Catawba Nuclear Station
Units 1 and 2
Docket Nos. 50-413, -414



Dear Mr. O'Reilly:

On March 1, 1982 your office was notified of a potentially reportable item pursuant to 10 CFR 50.55(e). The significant deficiency report SD 413-414/82-06 concerning undersized socket welds was to be submitted by March 31, 1982. At this time the evaluation of the reinspection efforts has not been completed. The evaluation will be completed and the report will be submitted by April 16, 1982.

Very truly yours,



William O. Parker, Jr.

RWO/php

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

P. K. Van Doorn
NRC Resident Inspector
Catawba Nuclear Station

OFFICIAL COPY

1827
1/0