

CONTROL BLOCK:

--	--	--	--	--	--

 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	1	5	7	0	3	2	2	8	2	3	0	4	1	3	8	2	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

0 2 | DURING NORMAL OPERATION, CONTROL ROOM AIR HANDLING UNIT, 1-HV-ACRA-1,
0 3 | WAS REMOVED FROM SERVICE TO REPLACE A BROKEN FAN BELT. THIS CONSTITUTED
0 4 | AN INOPERABLE HEATING AND COOLING TRAIN, CONTRARY TO T.S. 3.7.5.1. THE
0 5 | REDUNDANT TRAIN REMAINED OPERABLE AND PUBLIC HEALTH AND SAFETY WERE NOT
0 6 | AFFECTED.
0 7 |
0 8 |
7 8 9

09		SYSTEM CODE S G 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMPONENT CODE B L O W E R 14				COMP SUBCODE Z 15		VALVE SUBCODE Z 16			
7 8		9 10		11 12		13 14		15 16 17 18				19 20					
17		EVENT YEAR 8 2 21 22		SEQUENTIAL REPORT NO. 0 1 6 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30 31		REVISION NO. 0 32							
ACTION TAKEN A 18 33		FUTURE ACTION Z 19 34		EFFECT ON PLANT Z 20 35		SHUTDOWN METHOD Z 21 36		HOURS 0 0 0 0 22 37 40		ATTACHMENT SUBMITTED N 23 41		NPRO-4 FORM SUB N 24 42		PRIME COMP. SUPPLIER A 25 43		COMPONENT MANUFACTURER B 5 1 5 26 44 47	

1 0 THE FAILED BELT SHOWED NO SIGNIFICANT EVIDENCE OF WEAR. A NEW PAIR OF BELTS
1 1 WERE INSTALLED. THE BELTS ON THE REDUNDANT FAN AND SIMILAR FANS IN UNIT 2
1 2 WERE INSPECTED.
1 3
1 4

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	1	0	0	29	NA	30
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		OPERATOR OBSERVATION		LOCATION OF RELEASE	
1	6	Z	33	Z	34	NA	35	NA	36
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	39
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	40	NA	41	NA	42
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42	NA	43	NA	44	NA	45
PUBLICITY		ISSUED		DESCRIPTION					
2	0	N	44	NA	45	NA	46	NA	47

PHONE: 616-465-5901