



DESIGNATED CERTIFICATE

Certified By

Blocket #

50-311

Public Service Electric and Gas Company P.O. Box E Hancocks Bridge, New Jersey 08038

Salem Generating Station

June 4, 1982

Mr. R. C. Haynes
Regional Administrator
USNRC
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Haynes:

REPORTABLE OCCURRENCE 82-040/01P
SALEM NO. 2 UNIT LER

This letter is to confirm our verbal report to the NRC Headquarters on Wednesday, May 19, 1982, advising of a potential reportable occurrence in accordance with IE Bulletin 80-24.

During routine power operation, a service water leak was discovered inside the Containment Building, on No. 22 Containment Fan Coil Unit. The leak rate was approximately 1.5 gallons per minute, and the leak has been isolated.

Further reporting of the incident was inadvertently overlooked due to another incident occurring concurrently on No. 22 Containment Fan Coil Unit. Unit 2 LER 82-040/01T will be submitted explaining the circumstances surrounding this incident.

Sincerely yours,

H. J. Midura
General Manager -
Salem Operations

RF:ks

CC: Distribution