

**Detroit  
Edison**

Donald A. Wells  
Manager Quality Assurance  
(313) 237-9657

2000 Second Avenue  
Detroit, Michigan 48226  
(313) 237-8000

50-41  
May 21, 1982  
EF2-58068

Mr. James G. Keppler, Regional Administrator  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Subject: Interim Report of 10CFR50.55(e) on Defects in Eberline  
Instrument Corporation Radiation Monitoring Equipment (#67)


Dear Mr. Keppler:

On April 23, 1982, Detroit Edison's Mr. H.A. Walker, Supervisor-Construction Quality Assurance, telephoned Mr. H. Wescott of NRC Region III, to report on a problem with defects in Eberline Instrument Corporation Radiation Monitoring Equipment at the Fermi 2 site.

This item deals with defects in Eberline Instrument Corporation's radiation monitoring equipment which had been supplied to the Fermi 2 site. A letter was received from the NRC site resident inspector documenting a 10CFR21 report on the Eberline Instrument problem. Although the letter indicates Detroit Edison was notified of the problem by Eberline, we have not been able to locate the report or the letter. Detroit Edison has verified that the affected equipment was received, and was in use at the Fermi site.

Another report on this item, either interim or final, is scheduled to be sent to you on or before September 17, 1982. If you have questions concerning this matter, please contact Mr. H.A. Walker, Supervisor-Construction Quality Assurance.

Very truly yours,



DAW/HAW/cp

cc: Mr. Richard DeYoung, Director  
Office of Inspection and Enforcement  
Division of Reactor Inspection Programs  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. Bruce Little, Resident Inspector  
U.S. Nuclear Regulatory Commission  
6450 North Dixie Highway  
Newport, Michigan 48166

8206150333 820521  
PDR ADOCK 05000341  
S PDR

JUN 9 1982

IE19