



UNIVERSITY OF MISSOURI

Research Reactor Facility

May 25, 1982

Research Park
Columbia, Missouri 65211
Telephone (314) 882-4211

Director of Licensing
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Reference: a) Docket 50-186, License R-103
University of Missouri Research Reactor

b) Letter to Nuclear Regulatory Commission,
Director of Licensing, dated March 20, 1981

Subject: Modification to corrective
action contained in reference (b).

Dear Sir:

In our letter dated March 20, 1981, to the U. S. Nuclear Regulatory Commission, we informed you about an event in which a valve in a 3/4 inch line that penetrates the containment wall and is open ended on both sides was left open. Our corrective action included installing a pipe cap on the end of the pipe inside containment and hanging red "Danger" tags on the valves located outside of containment. The red tags have been removed due to the pipe cap inside containment being sufficient to insure this flow path is isolated and the use of red tags in this situation could degrade their significance, which would decrease the safety provided by their use. After reviewing this use of red tags, the Reactor Safety Subcommittee recommended the above change to the corrective action.

Sincerely,


J. C. McKibben
Reactor Manager

JCMK:vs

cc: NRC - Region III

A020

8206170229 820525
PDR ADOCK 05000186
S PDR



COLUMBIA KANSAS CITY ROLLA ST. LOUIS

an equal opportunity institution