



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

June 18, 1982
RBG-12,858
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Final Report/DR-54

On May 24, 1982, Gulf States Utilities Company (GSU) notified the Nuclear Regulatory Commission Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning B. F. Shaw rolled plate pipe with internal mismatches at seam welds, out-of-roundness, and existence of laminar discontinuities (DR-54). GSU has completed its review and determined that the deficiency is not reportable under 10CFR50.55(e). This concludes GSU's response on this item.

Sincerely,


J E Booker

J. E. Booker
Manager-Engineering & Licensing
River Bend Nuclear Group

WJS/RJK/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE-27



8206290419 820618
PDR ADOCK 05000458
S PDR