

RECEIVED  
TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II  
JUN 25 10 56 AM '82

June 21, 1982

BLRD-50-438/81-31

BLRD-50-439/81-34

U.S. Nuclear Regulatory Commission  
Region II

Attn: Mr. James P. O'Reilly, Regional Administrator  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:


BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - DEFICIENT PIPE SUPPORTS -  
BLRD-50-438/81-31, BLRD-50-439/81-34 - FINAL SUPPLEMENTAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector P. Taylor on April 6, 1981 in accordance with 10 CFR 50.55(e) as NCR BLN BLP 8109. This was followed by our first interim report dated May 6, 1981, our final report dated September 3, 1981, and our revised final report dated September 28, 1981. NRC-OIE Inspector R. V. Crlenjak was notified by telephone on December 15, 1981 that the nonconforming condition described in NCR BLN BLP 8130 had been discovered as a result of a design review which took place as part of the corrective action necessary to resolve NCR BLN BLP 8109. This was followed by our first supplemental report dated January 11, 1982. Because NCR BLN BLP 8109 was closed in inspection report 50-438/82-06, 50-439/82-06, NCR BLN BLP 8130 will now be reported as a separate item under 10 CFR 50.55(e).

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

  
L. M. Mills, Manager  
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

8206300173 820621  
PDR ADOCK 05000438  
S PDR

An Equal Opportunity Employer

OFFICIAL COPY

18 27