

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

June 21, 1982

Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. Ronald C. Haynes
Regional Administrator - Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King Of Prussia, PA 19406


Dear Mr. Haynes:

In accordance with Technical Specifications 3.13.A.2 and 6.9.2.d, the following report regarding an inoperable motor-driven fire pump is being submitted.

On May 20, 1982 at 8:00 AM, No. 12 Fire Pump was removed from service to repair a leaking packing gland. Subsequently, it was determined that the pump required overhaul and the pump was overhauled. Following the completion of the work, a post-maintenance test was performed which revealed leaks in the packing material. The leaks were repaired. The post-maintenance test was repeated with satisfactory results. The pump was returned to service at approximately 3:00 PM on May 27, 1982.

Should you or your staff have questions, please contact us.

Sincerely,



cc: Mr. T. Rebelowski, Resident Inspector
U. S. Nuclear Regulatory Commission
Post Office Box 38
Buchanan, N. Y. 10511

8207070186 820621
PDR ADOCK 05000247
S PDR

Special Report
IE 22