



FLORIDA POWER & LIGHT COMPANY

82 JUL 20 4 08:52  
July 14, 1982  
L-82-287

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: St. Lucie Unit 2  
Docket No. 50-389, 10 CFR 50.55 (e) 82-009  
Charging Pump and By-pass Valve Control Circuitry Failure

On June 2, 1982, Florida Power and Light Company (FPL) notified the Region II Office of Inspection and Enforcement, in accordance with the requirements of 10 CFR 50.55(e), of a potential deficiency regarding the failure of the charging pump and by-pass valve control circuitry to perform its intended function. FPL is still reviewing this problem to confirm whether it is a reportable deficiency under the regulations. A final report will be submitted by August 2, 1982.

Yours very truly,

Robert E. Uhrig  
Vice President  
Advanced Systems and Technology

REU/cab

cc: Director of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555