

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

June 29, 1990

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Serial No.: 90-226A
NAPS/JHL
Docket Nos.: 50-338
50-339
License Nos.: NPF-4
NPF-7

Gentlemen:


VIRGINIA ELECTRIC AND POWER COMPANY
NORTH ANNA POWER STATION UNITS 1 AND 2
SUPPLEMENTAL RESPONSE TO THE NOTICE OF VIOLATION
NRC INSPECTION REPORT NOS. 50-338/90-04 AND 50-339/90-04

NRC Inspection Report Nos. 50-338/90-04 and 50-339/90-04 dated April 13, 1990 cited North Anna Unit No. 1 with a violation for failure to take timely corrective action for repair of the B Low Head Safety Injection Pump (1-SI-P-1B). The cause of the violation was stated to be a purchasing error in that the purchase order to procure the necessary parts was cancelled because the order did not meet the minimum billing requirements. Further, we committed to develop a purchasing procedure to preclude the error of not meeting the minimum requirements for billing by June 1990.

We have performed a review of the corrective actions that were to be implemented and have determined that the violation was an isolated personnel error. The Virginia Electric and Power Company Nuclear Purchasing Guideline Manual delineates the steps to be taken when placing a purchase request on hold. Specifically, the Requisitioning Group is advised in writing when a problem exists, and makes the appropriate disposition according to a written response received from the Requisitioning Group. Therefore, an additional purchasing procedure will not be required.

If you have any further questions, please contact us.

Very truly yours,



W. L. Stewart
Senior Vice President - Nuclear

TEO1
1/0

cc: U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, N. W.
Suite 2900
Atlanta, Georgia 30323

Mr. M. S. Lesser
NRC Senior Resident Inspector
North Anna Power Station