


James A. FitzPatrick  
Nuclear Power Plant  
P.O. Box 41  
Lycoming, New York 13093  
315 342-3840



Harry P. Salmon, Jr.  
Resident Manager

October 1, 1993  
JAFF-93-0521

United States Nuclear Regulatory Commission  
Document Control Desk  
Mail Station P1-137  
Washington, D.C. 20555

SUBJECT: DOCKET NO. 50-333  
LICENSEE EVENT REPORT: LER-93-018-01: Incomplete  
Functional  
Testing of  
Carbon Dioxide  
Fire  
Suppression  
System

Dear Sir:

This updated report is submitted in accordance with 10CFR50.73 (a)(2)(i)(B). This supplement identifies that an increase in the minimum carbon dioxide storage tank level specified in the Technical Specification is required to provide a single full discharge of Carbon Dioxide into the North Emergency Switchgear Room. The supplement also identifies that six Carbon Dioxide discharge timer settings were found set less than the time required by JNRC-78-53, dated October 23, 1978.

Questions concerning this report may be addressed to Mr. Donald Simpson at (315) 349-6361.

Very truly yours,

A handwritten signature in cursive script, appearing to read "Harry P. Salmon, Jr.", written over the typed name.

HARRY P. SALMON, JR.

HPS:DES:tld

Enclosure

cc: USNRC, Region I  
USNRC Resident Inspector  
INPO Records Center

9310070064 931001  
PDR ADOCK 05000333  
S PDR

Handwritten initials "TLD" and the date "11/1" are written in the bottom right corner of the page.