



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401-1927  
Telephone (612) 330-5500

November 23, 1993

Report Required by  
10 CFR Part 50, Section 50.73

US Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT  
Docket No. 50-263 License No. DPR-22

Main Control Room Emergency Filtration Train  
Outside Design Basis Caused by In-leakage Across Inlet Dampers

The Licensee Event Report for this occurrence is attached. This report contains the following new NRC commitments.

The lessons learned from this event will be presented in Engineering Technical Staff Continuing Training.

Improved preventive maintenance and/or test procedures will be developed for the Control Room Ventilation-Emergency Filtration Train dampers.

The Operating Experience Assessment process will be revised to enhance requirements for establishing and monitoring appropriate follow-up action priorities.

Long term corrective actions to address this damper in-leakage concern will be evaluated.

Please contact Marv Engen, Sr Licensing Engineer, at (612) 295-1291 if you require further information.

Roger O Anderson  
Director  
Licensing and Management Issues

c: Regional Administrator - III, NRC  
NRR Project Manager, NRC  
Sr Resident Inspector, NRC  
State of Minnesota  
Attn: Kris Sanda

Attachment

9312020507 931123  
PDR ADOCK 05000263  
S PDR

JE22