

LICENSEE EVENT REPORT

CONTROL BLOCK 

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME					LICENSE NUMBER								LICENSE TYPE					EVENT TYPE					
01	M	N	M	N	P	1	0	0	-	0	0	0	0	-	0	0	4	1	1	1	1	0	1
7	8	9				14	15									25	26					31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER							EVENT DATE					REPORT DATE									
01	CONT	P	O	I	L	0	5	0	-	0	2	6	3	1	1	1	8	7	5	1	1	2	6	7	5
7	8	57	58	59	60	61							68	69						75					80

EVENT DESCRIPTION

Q2 During test, RCIC turbine failed to start when given a fast start. Failure was
Q3 due to the steam control valve sticking closed. Valve stem and pivots were
Q4 polished and lubricated. Operability and fast start capability demonstrated.
Q5 No previous similar events. (AO 263/75-26)
Q6

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIMARY COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION	
0	0	C	E	V	A	I	V	E	X	N	T	1	4	7	N
7	8	9	10	11	12	13	14	15	16	43	44	45	46	47	48

CAUSE DESCRIPTION

08	Corrosion products and crud on valve stem and pivots caused binding of valve.	80
09	Stem and pivots polished and lubricated. Terry Turbine Type GS-1.	80
10		80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE	AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
7	8	9	10	11	44	50
1	2	Z		NA		NA

PERSONNEL EXPOSURES

PERSONNEL INJURIES

OFFSITE CONSEQUENCES

LOSS OR DAMAGE TO FACILITY

PUBLICITY

ADDITIONAL FACTORS

9105070365 751126
CF ADDCK 05000263
CF

NAME R. A. Goranson

PHONE 612/295-5151