

ENRGO REGION II  
ATLANTA, GEORGIA

DEC 27 AIO: 34



December 20, 1982  
L-82-547

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: ST. LUCIE UNIT 2  
DOCKET NO. 50-389, 10 CFR 50.55(e), 82-020  
LACK OF DOCUMENTATION ON CLASS I AND II BOLTS AND NUTS

On October 13, 1982, Florida Power and Light Company (FPL) notified the Region II Office of Inspection and Enforcement in accordance with the requirements of 10 CFR 50.55(e) of a potential deficiency regarding the lack of documentation on Class I and II bolts and nuts. An interim report submitted on November 15, 1982 stated that a final report would be submitted on December 22, 1982. FPL is still reviewing this problem and will submit a final report by January 26, 1983.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems and Technology

REU/ok

cc: Director of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

OFFICIAL COPY

8212300252 821220  
PDR ADOCK 05000389  
S PDR

IE 27