

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

January 5, 1983

TELEPHONE
(704) 373-4531

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station
Docket Nos. 50-369 and 50-370

Reference: RII:WPA
50-369/82-42, 50-370/82-37 *TH*

Dear Mr. O'Reilly:

Duke Power Company does not consider any information contained in IE Inspection Report Nos. 50-369/82-36 and 50-370/82-30 to be proprietary. Please note that my letter to you (dated November 19, 1982) was Duke Power's final response concerning Containment Spray Heat Exchanger Foundation, Unit 1 ("Details" section, page 3, paragraph 7). Generic implications of a quality assurance problem will be looked into during the Unit 1 outage scheduled for January 15, 1983. A report shall be filed only if a problem is identified.

Very truly yours,

H.B. Tucker / BT

Hal B. Tucker

WHM/php

cc: Senior Resident Inspector
McGuire Nuclear Station

8301250578 830105
PDR ADOCK 05000369
PDR
Q

IE01