

APPROVED BY OMB
3150-0011
EXPIRES 4-30-82

Attachment

Licensee Event Report 82-073/03L-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (Item #27 continued):

A temporary modification has moved the sensor to the sample line, and the necessary paperwork will be initiated to make this change a permanent modification.