

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01
NYNMP1
200-00000-00
341111
4
5

CON'T

01
REPORT SOURCE L60500022071218828011183
9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During a major maintenance outage while performing local leak rate testing, leakage

03 from the valves 201.2-27 and 201.2-28 were found to exceed Technical Specifications.

04

05

06

07

08

09

SD 11
E 12
X 13
VALVEX 14
F 15
D 16

82
022
03
L
0

ZB
Z
Z
0000
N
Y
X
L087

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Failures were attributed to dirt and corrosion resulting in poor seating. These valves

11 will be cleaned during the current outage, followed by a retest.

12

13

14

15
G28
000
NA
B31 Test Results

16
Z33
Z34
NA
NA

17
000
Z
NA

18
000
NA

19
Z
NA

20
N

8301260370 830112
 PDR ADOCK 05000220
 S PDR

NRC USE ONLY

NAME OF PREPARER M. Burgmeier

PHONE (315) 349-2616