

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01
NYNMP1
200-00000-00
341111
45

LICENSEE CODE

LICENSE NUMBER

LICENSE TYPE

CAT 58

CON'T

01
L605000220
7121882
8011183
9

REPORT SOURCE

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During a major maintenance outage while performing local leak rate testing, leakage  
03 from the valve 201.2-71 was found to exceed Technical Specifications. LER 81-09  
04 reported a similar occurrence.  
05  
06  
07  
08

09
SD11
E12
X13
VALVEX14
C15
D16

17 LER NO. 82
023
03
L
0

Z18
B19
Z20
Z21
0000
N23
Y24
X25
C33926

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 This failure was attributed to dirt and corrosion resulting in poor seating. This  
11 valve will be cleaned during the current outage, followed by a retest.  
12  
13  
14

15
G28
00029
NA
B31
Test Results

16
Z33
Z34
NA
NA

17
00037
Z38
NA

18
00040
NA

19
Z42
NA

20
N44

8301260375 830112  
PDR ADOCK 05000220  
S PDR

NRC USE ONLY

NAME OF PREPARER M. Burgmeier

PHONE (315) 349-2616