

LICENSEE EVENT REPORT

Attachment to AECM-83/43

Page 1 of 1

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	S	G	G	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	9						14	15	25										26	30					57	58		
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE						CAT			

CON'T

0 1 7 8 REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 1 2 2 7 8 2 8 0 1 2 0 8 3 9 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On December 27, 1982, a Division 2 Diesel Generator trouble alarm was received in the

0 3 | Control Room. Investigation revealed that the diesel generator failure to start alarm

0 4 | was activated on the local panel. Diesel Generator 12 and Division 2 ECCS were

0 5 | declared inoperable. LCO's were entered under both T.S.3.5.2 and T.S.3.8.1.2. This

0 6 | event had no effect on the health and safety of the public and did not constitute a

0 7 | threat to plant safety. This event is reported pursuant to T.S.6.9.1.13.b.

0 8 | _____

SYSTEM CODE E B 11		CAUSE CODE E 12		CAUSE SUBCODE G 13		COMPONENT CODE I N S T R U 14				COMP. SUBCODE X 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 2 21 22		SEQUENTIAL REPORT NO. 1 7 4 24 25 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32									
ACTION TAKEN B 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD 21		HOURS 0 0 0 22 37 40		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER R 3 6 3 26 44 47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 It was discovered that the circuit card for the failure to start alarm had failed.

1 1 An identical card was installed in the local annunciator panel and the failed card

1 2 was repaired. Once the card was replaced Diesel Generator 12 and Division 2 ECCS

1 3 were returned to service on December 28, 1982. This is a final report.

1 4

8 9
FACILITY STATUS (1) (5) (B) (28) % POWER (0) (0) (0) (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (A) (31) Alarmed Condition DISCOVERY DESCRIPTION (32)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
(1) (6) (Z) (33) (Z) (34) NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA
(1) (7) (0) (0) (0) (37) (Z) (38)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
PERSONNEL INJURIES NUMBER DESCRIPTION (31) NA
(1) (8) (0) (0) (0) (40)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43) NA
(1) (9) (Z) (42)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
PUBLICITY ISSUED DESCRIPTION (45) 8301260456 830120 PDR ADOCK 05000416 S PDR
(2) (0) (N) (44)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60
NRC USE ONLY
68 69 70

NAME OF PREPARER Original signed by M. Scott Freeman

PHONE