

**LICENSEE EVENT REPORT**

Attachment to AECM-83/76

Page 1 of 1

CONTROL BLOCK: 

						(1)
--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	S	G	G	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT		58

CON'T

0 1 7 8 REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 1 2 2 2 8 2 8 0 2 0 3 8 3 9  
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On December 22, 1982, the smoke detection zone covering the Auxiliary Building  
0 3 | corridor area (elevation 139 feet) alarmed and would not reset. Investigation  
0 4 | revealed no smoke or fumes present in the area. A fire watch was established  
0 5 | pursuant to T.S.3.3.7.9. This event had no effect on the health and safety of the  
0 6 | public and did not constitute a threat to plant safety. This is a Special Report  
0 7 | filed pursuant to T.S.3.3.7.9.b.

08		7		8		9		90							
SYSTEM CODE				CAUSE CODE		CAUSE SUBCODE		COMP. SUBCODE				VALVE SUBCODE			
A		B		X		Z		I N S T R U				E			
9		10		11		12		13				14			
19		20		21		22		23				24			
EVENT YEAR				SEQUENTIAL REPORT NO.		OCCURRENCE CODE				REPORT TYPE		REVISION NO.			
8		2		1		8		3		9		9			
21		22		23		24		25		26		27			
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.			
X		Z		Z		Z		0		N		N			
33		34		35		36		37		38		39			
40		41		42		43		44		45		46			
47		48		49		50		51		52		53			
54		55		56		57		58		59		60			
61		62		63		64		65		66		67			
68		69		70		71		72		73		74			
75		76		77		78		79		80		81			
82		83		84		85		86		87		88			
89		90		91		92		93		94		95			
96		97		98		99		100		101		102			
103		104		105		106		107		108		109			
110		111		112		113		114		115		116			
117		118		119		120		121		122		123			
124		125		126		127		128		129		130			
131		132		133		134		135		136		137			
138		139		140		141		142		143		144			
145		146		147		148		149		150		151			
152		153		154		155		156		157		158			
159		160		161		162		163		164		165			
166		167		168		169		170		171		172			
173		174		175		176		177		178		179			
180		181		182		183		184		185		186			
187		188		189		190		191		192		193			
194		195		196		197		198		199		200			
201		202		203		204		205		206		207			
208		209		210		211		212		213		214			
215		216		217		218		219		220		221			
222		223		224		225		226		227		228			
229		230		231		232		233		234		235			
236		237		238		239		240		241		242			
243		244		245		246		247		248		249			
250		251		252		253		254		255		256			
257		258		259		260		261		262		263			
264		265		266		267		268		269		270			
271		272		273		274		275		276		277			
278		279		280		281		282		283		284			
285		286		287		288		289		290		291			
292															

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Upon investigation by maintenance, the smoke detection zone was found functionally

1 1 | operable and was reset. The cause of the alarm is attributed to spurious actuation.

1 2 | The zone was restored to operability on January 12, 1983. This is a final report.

1 3 |

1 4 |

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
1	5	G	28	0	0	0	29	NA	A	31	Alarmed Condition
7	8	9	10	11	12	13	14	15	16	17	18
ACTIVITY CONTENT		RELEASED OF RELEASE			AMOUNT OF ACTIVITY		LOCATION OF RELEASE				
1	5	Z	33	Z	34	NA	35	NA	36		
7	8	9	10	11	12	13	14	15	16	17	18
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION					
1	7	0	0	0	37	Z	38	NA			
7	8	9	10	11	12	13	14	15	16	17	18
PERSONNEL INJURIES		NUMBER		DESCRIPTION							
1	5	0	0	0	40			NA			
7	8	9	10	11	12	13	14	15	16	17	18
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION		8302140060 830203 PDR ADOCK 05000416 S PDR					
1	9	Z	42			NA					
7	8	9	10	11	12	13	14	15	16	17	18
PUBLICITY		ISSUED		DESCRIPTION		NRC USE ONLY					
2	0	N	44			NA					
7	8	9	10	11	12	13	14	15	16	17	18

NAME OF PREPARER Original signed by M. Scott Freeman

PHONE: \_\_\_\_\_